•					,									
Work Order ID 59745 Thursday, June 10, 2010 11:25:26 AM								·					Page	1
Item ID: Revision ID:	D4019-3			Accept						Setup	Start			
Item Name:	Rib										Stop			
Start Date: Required Date: Reference:	6/10/2010 6/17/2010	Start Qty: 6.00 Req'd Qty: 6.00				Cust Item I Customer:	D:					1 188111181 8		
Approvals:	Process Plan	n:	Date: <u>  6                                  </u>	Tooling	-		nte:		]	Run	Start Stop			
Sequence ID/ Work Center II	)	Operation Description		Set 1 Run	Up/ Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp	_
Draw Nbr	Revi	sion Nbr												_
D4019	C													
100 		Memo		0.00					6				.,,,,,	_
Large Fab		1- Cut tu	be as per dwg D4019 e identification marks and deb		CAS	10-0	6-19	H						
1 10 		QC5- Inspect part cor	npleteness to step on W/O	0.00		1				\				
QC Quality Control		Memo		0.00	obi S	6/64			(46	))				

120

Packaging

Packaging

Memo

Identify as per dwg & Stock Location: WA

0.00 SAD 10-66-84

Dart Aerosp	ace Ltd
-------------	---------

W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA	<b>\</b> :	Date: _						
Resolution:		olution:			Date:	_ Date:								
NCR:		1	WORK ORD	ER NON-CONFORMA	NCE (NCF	<b>r</b> )								
DATE	STEP	Description of NC	ription of NC Corrective Action				ication Approval		Approval					
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section	on C	Chief Eng	QC Inspector					
								:						
			·											
			·			:								
			\											

W	ork	Ord	er ID	597	45
7 7		$\mathbf{v}_{\mathbf{i}}$	vi il	271	_

Thursday, June 10, 2010 11:25:26 AM



Page 2

Item ID:

D4019-3

Accept

Setup Start

Stop

**Revision ID:** 

**Start Date:** 

Item Name: Rib

Required Date: 6/17/2010

6/10/2010

Start Qty: 6.00

Req'd Qty: 6.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:	Process Plan:	Date:	Tooling:	Date:	Run	Start	
	QC:	Date:	SPC (Y/N):	Date:		Stop	

Sequence ID/ Work Center ID

Set Up/ **Run Hours** 

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Reject Insp. Number Stamp

130

Quality Control

Memo

-mF 10-6-15

Operation Description

QC21- Final Inspection - Work Order Release

0.00

	•													
W/O:			W	ORK ORDER CHA	NGES									
DATE	STEP	PRO	l	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
			10.											
Part No:				Fault Category:NC				NCR: Yes No DQA: Date:						
Resolution:			Disposition	QA: N	_ QA: N/C Closed: Date									
NCR:			WORK ORD	ER NON-CONFOR	RMANCE (	NCR)								
DATE	STEP	Description of NC	Initial	Section B Verif			ication Approva							
		Section A	Chief Eng	Action Description Chief Eng	on s	Section C		Chief Eng	QC Inspector					
				W. C. Waller Inc.										
									:					
· · · · · ·				-										

## **Picklist Print**

Thursday, June 10, 2010 11:25:30 AM

Work Order ID: 59745

Comments:

Parent Item: D4019-3

Parent Item Name:

Rib

IPP RevA: new issue DD 10.01.25 verified by:EC

per dwg revA 10.03.15 verified by:EC DD 10.04.20 verified by:EC



**Start Date:** 6/10/2010

Required Date: 6/17/2010

Page 1

Start Qty: 6.00

Required Qty: 6.00

IPP Rev:B as

IPP Rev:C as per dwg revC




6061-T6 SQ Tube .75 x .75 x .062W

	SAO	10-06-14
--	-----	----------


<b>Location</b>		Loc Oty	Loc Code	
MAT		108.4213		
1	14573	22.1055		
1	14640	86.3158		11.05263
MAT06	,	77.6752		
1	103069	38.0526		
1	04422	15.5263		
1	6441	4.07		<del></del>
9	0671	20.0263		

	•													
W/O:		WORK ORDER CHANGES												
DATE STEP		PR		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
									] :					
Part No	•	PAR #:	Fault Cate	gory:	NCR:	Yes I	No DQ	<b>A</b> :	Date: _					
Resolution:														
NCR:				R NON-CONFORM					,,,,,					
DATE	STEP	Description of NC		ection B Veri			fication Approval		Approval					
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section C	Chief Eng	QC Inspector					
		, , , , , , , , , , , , , , , , , , , ,												




Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:			wc	RK ORDER CHANG	GES					
DATE STEP		PRO	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
									3	
								:		
			100							
_										
					NCR: Yes No DQA: Date:					
			Disposition: Q							
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)				
DATE	STEP	Description of NC	Corrective Action Section			Verific	cation	Approval	Approval	
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		on C	Chief Eng	QC Inspector	
							į			
					····					
					·					




## **Dart Aerospace Ltd**

W/O:			V	ORK ORDER CHAN	GES						
DATE STEP		PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
							10				
Part No	<b>:</b>	PAR #:	Fault Ca	tegory:	NCR:	Yes I	No DQ	A:	Date:		
				Disposition: Q/							
NCR:			WORK OR	DER NON-CONFORM	IANCE	(NCR	)				
DATE	STEP	Description of NC	B	Corrective Action Section				ation	Approval	Approval	
	0121	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector	
										•	



## **Dart Aerospace Ltd**

		W	ORK ORDER CHANG	iES	,,	<del> </del>				
STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspector		
						<u> </u>				
				NCR: Yes No DQA: Date:						
			Disposition: QA							
		WORK ORI	DER NON-CONFORM	ANCE (NCF	R)					
STEP	Description of NC	Initial			cation Approv	Approval	Approval			
	Section A	Chief Eng	Chief Eng	Date			Chief Eng	QC Inspector		
								,		
		:PAR #:PAR #:	STEP PROCEDURE CHECK  PAR #: Fault Care Resolution: Disposite  WORK ORI  STEP Description of NC Section A Initial	STEP PROCEDURE CHANGE  PROCEDURE CHANGE  Fault Category:  Disposition:  WORK ORDER NON-CONFORM  STEP Description of NC Section A  Initial Action Description	PAR #: Fault Category: NCR: Yes  Resolution: Disposition: QA: N/C CI  WORK ORDER NON-CONFORMANCE (NCF  STEP Description of NC Section A   Corrective Action Section B    Initial Action Description Sign 8	STEP PROCEDURE CHANGE By Date  PAR #: Fault Category: NCR: Yes No DQ/ Resolution: Disposition: QA: N/C Closed:  WORK ORDER NON-CONFORMANCE (NCR)  STEP Description of NC Section A Corrective Action Section B Verific Section A Section B Sign & Verific Section A Section B Section A Section B Se	STEP PROCEDURE CHANGE By Date Qty	STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr		



Dart Aerospace	Ltd
----------------	-----

W/O:			V	ORK ORDER CHANC	GES						
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
					į						
						-					
Part No:		PAR #:	Fault Category: NCR: Yes No DQA:						_ Date: _		
Resolution:			Disposit	Disposition: Q			QA: N/C Closed: Date:				
NCR:			WORK OR	DER NON-CONFORM	ANCE (N	ICR)					
DATE	STEP	Description of NC	Corrective Action Section					ation	Approvai	Approval	
	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		gn & Date	Section C		Chief Eng	QC Inspector	
										,	
		•			:						
· · · · · · · · · · · · · · · · · · ·								11.			
			3								
						**************************************			-		
					1						